

Transformers from 100 to 5,000 kVA



Output in kVA	Overtoltage	Undervoltage	Details:
100	500-600-660-690	400	autotransformer
250	500-600-660-690	400	autotransformer
630	500-600-660-690	400	autotransformer
1.000	500-600-660-690	400	autotransformer
1.250	2.993 bis 11.458	400	galvanic isolation
1.600	6.060 oder 10.500	400	galvanic isolation
2.500	9.500 bis 21.000	400	galvanic isolation
5000 (2x 2.500)	9.500 bis 21.000	400	galvanic isolation